

STANDARD DEPARTURE CHART -INSTRUMENT

RJAA / NARITA INTL

TRANSITION (B)

HAKONE TRANSITION

From over SAMMY, proceed via KZE R-069 to KZE VOR/DME, then via KZE R-247 to HYE VOR/DME.

Cross KZE VOR/DME at or above FL200.

HAKONE TRANSITION

