

## STANDARD DEPARTURE CHART-INSTRUMENT

RJBB / KANSAI INTL

TRANSITION

KAGAWA TRANSITION

After LINDA, proceed via KTE R-074 to GLORY or KTE VOR/DME.

KOCHI SOUTH TRANSITION

After TME VOR/DME, proceed via TME R-243/30DME, then KRE R-063 to KRE VOR/DME.

Cross TME R-243/30DME(KRE R-063/50DME) at or above 13,000FT, cross KRE R-063/26DME at or above FL160.

OGURA TRANSITION

From over NANKO, climb via CUE R-231 to OGURA.

NARAH TRANSITION

From over KNE VOR/DME, climb via KNE R-086 to NARAH.

KUSHIMOTO TRANSITION

After TME VOR/DME, proceed via TME R-174 to GBE VOR/DME, then via GBE R-136 to KEC VORTAC.

Cross GBE VOR/DME at or above 6,000FT.

SAYOH TRANSITION

From over MAIKO, proceed via SKE R-295 to OLIVE, turn right via AJE R-343 to SAYOH.

Cross OLIVE at or above 10,000FT.