

STANDARD DEPARTURE
ROUTES – INSTRUMENT
(SID)

SYLT
RWY 14/32

Designator	Route	After Take-Off		Remarks
		Climb to	Contact	
1	2	3	4	5
RWY 14				
LBE 5S	ELBE FIVE SIERRA On track 144° SLT to SLT(Δ); LT, on track 134° SLT to BARDU (Δ); RT, on R335 LBE to LBE (Δ). GPS/FMS RNAV: [A500+] - SLT[L] - BARDU[R] - LBE.	4000 ft	Bremen Radar 124.075	Not available for destination EDDH / EDHI / EDHL.
WSR 5S	WESER FIVE SIERRA On track 144° SLT to SLT (Δ); RT, on track 164° SLT to VEPOL (Δ); LT, on track 156° to OSTOR (Δ); RT, on R011 WSR to WSR (Δ). GPS/FMS RNAV: [A500+] - SLT[R] - VEPOL[L] - OSTOR[R] - WSR.			1. Between VEPOL and OSTOR BRNAV equipment necessary. 2. For destination EDDH / EDHI / EDHL proceed after OSTOR to RIBSO.
DHE 4S	HELGOLAND FOUR SIERRA On track 144° SLT to SLT(Δ); RT, on track 164° SLT to VEPOL (Δ); RT, on R055 DHE to DHE (Δ). GPS/FMS RNAV: [A500+] - SLT[R] - VEPOL[R] - DHE.			
RWY 32				
LBE 6N	ELBE SIX NOVEMBER On track 324° SLT to 3.0 DME WES; RT, on track 175° to SLT (Δ); on track 134° SLT to BARDU (Δ), on R335 LBE to LBE (Δ). GPS/FMS RNAV: [A500+] - XW100[R] - XW101 - SLT[L] - BARDU[R] - LBE.	4000 ft	Bremen Radar 124.075	Not available for destination EDDH / EDHI / EDHL.
WSR 6N	WESER SIX NOVEMBER On track 324° SLT to 3.0 DME WES; RT, on track 175° to SLT (Δ); on track 164° SLT to VEPOL (Δ); LT, on track 156° to OSTOR (Δ); RT, on R011 WSR to WSR (Δ). GPS/FMS RNAV: [A500+] - XW100[R] - XW101 - SLT[L] - VEPOL[L] - OSTOR[R] - WSR.			1. Between VEPOL and OSTOR BRNAV equipment necessary. 2. For destination EDDH / EDHI / EDHL proceed after OSTOR to RIBSO.
DHE 4N	HELGOLAND FOUR NOVEMBER On track 324° SLT to 3.0 DME WES; RT, on track 175° to SLT(Δ); on track 164° SLT to VEPOL (Δ); RT, on R055 DHE to DHE (Δ). GPS/FMS RNAV: [A500+] - XW100[R] - XW101 - SLT[L] - VEPOL[R] - DHE.			
(Sample: XW100 fly-over way point)				
<div style="border: 1px solid black; padding: 5px; display: inline-block;"> Contact Bremen Radar immediately after take-off! </div>				