

STANDARD DEPARTURE CHART -INSTRUMENT

RJAA / NARITA INTL

TRANSITION (E)

YAMIZO TRANSITION

From over TYE VOR/DME, proceed via TYE R-016 to TAKDA, then via GOC R-184 to GOC VORTAC.

IWAKI TRANSITION

From over TYE VOR/DME, proceed via TYE R-016 to TAKDA, then via TLE R-029 to SATMI, then via IXE R-226 to IXE VOR/DME.

TRANSITIONS

