

STANDARD DEPARTURE CHART -INSTRUMENT

RJAA / NARITA INTL

TRANSITION (F)

CHINO TRANSITION

From over TETRA, proceed via DYE R-079 to DYE VOR/DME, then via DYE R-293 to CHINO.

Cross DYE VOR/DME at or above FL200.

