

STANDARD DEPARTURE CHART-INSTRUMENT

RJFF / FUKUOKA

TRANSITION

KAFRI TRANSITION

From over YAMEK, turn right, proceed via IKE R-127 to KAFRI.  
Cross IKE R-127/37DME at or above 6000FT.

OITA TRANSITION

From over OGUNI, proceed via TAE R-272 to TAE VOR/DME.  
Cross TAE R-272/32DME at or above FL140, cross TAE R-272/27DME at or above FL170.

KUGA TRANSITION

From over OGUNI, proceed via IWC R-236 to IWC VORTAC.  
Cross IWC R-236/73DME (DGC R-132) at or above FL140,  
cross IWC R-236/66DME (DGC R-123) at or above FL170.

KAGOSHIMA TRANSITION

After YAMGA, proceed via HKC R-012 to HKC VORTAC.

KUMAMOTO TRANSITION

After YAMGA, proceed via KUE R-351 to KUE VOR/DME.

TAGAWA TRANSITION

From over YAMEK, turn left and proceed via TTE R-210 to intercept and proceed via DGC R-081 to IWC VORTAC.  
Cross TTE R-210/47DME (DGC R-140) at or above 6,000FT,  
cross TTE R-210/38DME (DGC R-110) at assigned altitude.

SAGA TRANSITION

After YAMEK, proceed via SGE R-058 to SGE VOR/DME.

OMUTA TRANSITION

From over YAMEK, proceed via TTE R-210 to OMTA.  
Cross TTE R-210/68DME(SGE R-097) at or above 10,000FT.

IKI TRANSITION

From over YAMEK, turn right, proceed via IKE R-127 to IKE VOR/DME (307DEG to IK NDB).  
Cross IKE R-127/37DME at or above 6,000FT.