

STANDARD DEPARTURE CHART-3 -INSTRUMENT

KROBE TRANSITION

From over HOUBA, proceed via KCC R-033 to KROBE.
Cross KCC R-033/60DME at or above FL200.

NIIGATA TRANSITION

From over HOUBA, proceed via KCC R-033 to KROBE then via GTC R-226 to
GTC VORTAC.
Cross KCC R-033/60DME at or above FL200.

