

STANDARD ARRIVAL CHART-3 - INSTRUMENT

(For RWY36)

TOPAT SOUTH ARRIVAL

From over TOPAT, proceed via TIC R-101, turn left via NHC 20DME clockwise ARC to intercept and proceed via NHC R-178 to GRASE.

Cross TIC R-101/46DME between 4,000FT and FL200, cross GRASE at or above 3,000FT.

ERABU ARRIVAL

From over ONC VORTAC, proceed via ONC R-222/NHC R-042, turn left via NHC 20DME clockwise ARC to intercept and proceed via NHC R-178 to GRASE.

Cross ONC R-222/31DME at or below FL200 and cross GRASE at or above 3,000FT.

CHERY ARRIVAL

From over CHERY, proceed via TIC R-050, turn left via NHC 20DME clockwise ARC to intercept and proceed via NHC R-178 to GRASE.

Cross TIC R-050/57DME at or below FL200, cross TIC R-050/45DME at or above 7,000FT and cross GRASE at or above 3,000FT.

TEBEK ARRIVAL

From over TEBEK, proceed via TIC R-225, turn right via NHC 20DME counter-clockwise ARC to intercept and proceed via NHC R-178 to GRASE.

Cross TIC R-225/60DME at or above 8,000FT, cross RAMBL at or below FL200, cross GRASE at or above 3,000FT.