

---

STANDARD DEPARTURE CHART-1 - INSTRUMENT

AGUNI TWO DEPARTURE

- RWY 18 : Turn right,....  
RWY 36 : Turn left,....  
....Climb via NHC R-309 to KERAM.  
Cross NHC R-309/15DME at 1,000FT.

DORIS FOUR DEPARTURE

- RWY 18 : Turn right HDG 200 DEG,....  
RWY 36 : Climb RWY HDG to 500FT or above, turn left HDG 190 DEG,....  
....Climb to intercept and proceed via 272 DEG from OK NDB to DORIS.  
Cross DORIS at or above 3,000FT.

NAHA SOUTHWEST FOUR DEPARTURE

- RWY 18 : Turn right,....  
RWY 36 : Climb RWY HDG to 500FT or above, turn left,....  
....Climb via NHC R-195 to MAZDA.  
Cross NHC R-195/6DME at 1,000FT.

OKINAWA TWO DEPARTURE

- RWY 18 : Turn left, proceed direct to OK NDB.  
RWY 36 : Climb RWY HDG to 500FT or above, turn left HDG 195 DEG to  
intercept and proceed via 110 DEG to OK NDB.  
Maintain 1,000FT until intercepting 110 DEG to OK NDB.

CHINEN TWO DEPARTURE

- RWY 18 : Turn left, proceed direct to OK NDB,....  
RWY 36 : Climb RWY HDG to 500FT or above, turn left HDG 195 DEG to  
intercept and proceed via 110 DEG to OK NDB.  
Maintain 1,000FT until intercepting 110 DEG to OK NDB,....  
.... Turn left via TIC R-248 to TIC VORTAC.

NAHA NORTH TWO DEPARTURE

- RWY 18 : (Not established)  
RWY 36 : Climb via NHC R-340 to EISAR.  
Cross NHC R-340/15DME at 1,000FT.

NAHA SOUTH REVERSAL TWO DEPARTURE

- RWY 18 : Climb via NHC R-190 until passing 2,100FT, then turn right, proceed  
to NHC VORTAC.  
RWY 36 : (Not established)