
AERODROME GROUND MOVEMENT AND AIRCRAFT PARKING CHART - ICAO TOWER 118.200 **GROUND** 119.000 APRON 118.800 SAMARA, RUSSIA

KURUMOCH



APRONS:

1. APRON TSENTRALNY:

Strength: Stands 3-6, 9-12, 45-49,

49A, 51-56, P - PCN 30/R/B/X/T (mixed)

- Asphalt-Concrete

- Asphalt-Concrete

2. SECTOR WEST:

Surface: Strength: Stands 15-27

3. SECTOR EAST

PCN 36/R/B/X/T (mixed)

Surface:

Strength: Stands 28-44

- Asphalt-Concrete - PCN 36/R/B/X/T (mixed)

4. Maintenance stands:

Surface: Strength: 7, 8, 13, 14 - Asphalt-Concrete

5. TWY 2

- PCN 11/R/B/X/T (mixed)

Surface: Strength: B

- Asphalt-Concrete - PCN 44/R/B/X/T (mixed)

TAXIWAYS:

Width:

Surface:

- 18m 1. 3 - 16m

5-11 - 22.5m

MAIN, 1-3, 11 - Asphalt-Concrete

5-10 - Concrete Strength:

- PCN 30/R/B/X/T (mixed) - PCN 44/R/B/X/T (mixed) - PCN 26/R/B/X/T (mixed)

5.6 - PCN 36/R/B/X/T - PCN 32/R/B/X/T 7-10

11 - PCN 46/F/D/X/T (mixed) - PCN 36/R/B/X/T (mixed) MAIN

WARNING:

- Taxiing-in/taxiing-out RWY 05/23 shall be carried out at minimum speed with great caution (the radius of junction of TWY 2, 3 and RWY is 30m).
 Taxiing of ACFT along TWY 1-3 and the apron shall be carried out
- under reduced engines power, with great caution of the flight crew, strictly along the taxi guideline. Taxiing along TWY 2 is allowed for ACFT with a wingspan of not more than 32m.
- 3. Taxiing of arriving ACFT along the apron shall be carried out under control of GROUND controller after the "FOLLOW ME" vehicle to the assigned stands. Taxiing of departing ACFT shall be carried out (as a rule) after the "FOLLOW ME" vehicle.

 Taxiing of ACFT with four or more on-wing mounted engines shall be
- carried out under reduced power of inner engines and at idle power of outer engines.
- or outer engines.

 5. Taxiing of ACFT shall be carried out strictly along the taxi guideline under reduced power of inner engines and at idle power of outer engines.

 6. Reserve stand is on RWY 05/23 in the vicinity of TWY 2 (when ACFT parking is more than twenty-four hours, a NOTAM to be issued about the presence of obstacle on RWY 05/23).

 7. Taxiing of II-76, II-86 ACFT shall be carried out strictly along the taxi
- guideline under reduced power of inner engines and at idle power of outer engines.
- Taxiing under own engines power is prohibited for:

 II-76 and II-86 ACFT on the apron segment between stands 15-27;
 II-76, II-86, II-62 and A-310 ACFT on the apron segment between

 stands 33-27, when stands 9-14, 49 are occupied abeam taxi route.