

STANDARD DEPARTURE CHART -INSTRUMENT

RJAA / NARITA INTL

SID (B)

PAPAS NINE DEPARTURE

RWY16R : Climb via NRE R-156 to 14DME,...

RWY16L : Climb via HKE R-156 to 15.4DME,...

...turn left to intercept and proceed via NRE R-137 to PAPAS.

Cross PAPAS at or above 7,000ft.

RWY34L : Climb via NRE R-336 to 6DME,...

RWY34R : Climb via HKE R-336 to 3.9DME,...

...turn right within NRE 10DME (RWY34L)/HKE 8.1DME(RWY34R),
proceed via OJC R-012 to intercept and proceed via NRE R-137 to
PAPAS.

Cross NRE R-015(RWY34L)/HKE R-014(RWY34R) at or below
7,000ft, cross PAPAS at or above 7,000ft.

Note 1 : Aircraft unable to comply with the flight restrictions, inform NARITA
DELIVERY for alternate procedure, when requesting ATC clearance.

Note 2 : When taking off from RWY 34L/RWY16L, following climb gradient
should be maintained until 630ft.

Speed (Knots)	60	90	120	150	180	210
Rate (Feet/Min)	300	450	600	750	900	1050

PAPAS NINE DEPARTURE

