

STANDARD DEPARTURE CHART-INSTRUMENT

RJCC / NEW CHITOSE

SID

HOKUTO FIVE DEPARTURE

RWY 01L/01R: Climb via RWY HDG until 1NM FM RWY end/CHE 6.3DME, turn right to intercept and proceed via CHE R-020, then via MKE R-352 to KURIS.

Cross CHE R-020/15DME (136 DEG from NA NDB) at or above 3,000ft, cross KURIS at or above 7,000ft.

RWY 19R/19L: Climb direct to CHE VOR/DME until 1.5DME prior to CHE VOR/DME (until crossing MKE R-320), turn left to intercept and proceed via CHE R-135 (MKE R-315) to CHE 5DME (MKE 10DME), then turn left to intercept and proceed via MKE R-352 to KURIS.

Cross CHE R-135/5DME (MKE R-315/10DME) at or above 3,000ft, cross MKE R-352/13DME at or above 5,000ft, cross KURIS at or above 7,000ft.

