

STANDARD DEPARTURE CHART -INSTRUMENT

RJAA / NARITA INTL

TRANSITION (A)

FAIRY TRANSITION

From over PAPAS, proceed via CVC R-167 to APPLE, via KZE 64DME clockwise ARC to TANUK, then via OJC R-204 to FAIRY or via OJC R-204 to join B586.

Cross KZE R-153 at or above 13,000FT, cross FAIRY at or above FL250.

CUPID TRANSITION

From over PAPAS, proceed via NRE R-137 to CUPID, via KZE 64DME clockwise ARC to TANUK, then via OJC R-204 to FAIRY or via OJC R-204 to join B586.

Cross CUPID at or above 8,000FT, cross KZE R-153 at or above 13,000FT, cross FAIRY at or above FL250.

APPLE TRANSITION

From over PAPAS, proceed via CVC R-167 to MERED.

PETAL TRANSITION

From over PAPAS, proceed via HME R-108 (107DEG from HM NDB) to join OTR20.

TRANSITIONS

