

STANDARD DEPARTURE CHART-4 - INSTRUMENT

**MORIZ ONE DEPARTURE**

RWY 34 : Climb RWY HDG to 500 FT or above, complete right turn within 4NM,....


RWY 16 : climb RWY HDG until 1NM from RWY end/KCC 2.5DME, turn left,....

....climb via KCC R-137 (136 DEG from KC NDB) to MORIZ.

(Cross MORIZ at or above 7,000FT for HAMAMATSU TRANSITION when using LHT TACAN.)

Note : Following climb gradient should be maintained until 2,500 FT.

Speed (Knots)	60	90	120	150	180	210
Rate (Feet/Min)	300	450	600	750	900	1050



(7000 for HAMAMATSU TRANSITION when using LHT TACAN)