

STANDARD ARRIVAL CHART-1 -INSTRUMENT

EXPOH SOUTH ARRIVAL

From over XMC VORTAC, proceed via XMC R-027 to 18DME, then turn left to intercept and proceed via KCC R-159 to EXPOH.
cross EXPOH at or above 2,500FT.

EXPOH NORTH ARRIVAL

From over SWING, proceed via XMC R-027 to 24DME, then turn right to intercept and proceed via KCC R-159 to EXPOH.

Cross XMC R-027/30DME at or above 5,000FT, cross EXPOH at or above 2,500FT.

